



Valley View Farm - Frequency Response Tests


Frequency response #1 Test 6-22-16 Pink noise inside hall




Frequency response Test 6-22-16 listening test Modern music inside hall




Frequency response Test 6-22-16 listening test Outside front door of Hall closed




Frequency response Test 6-22-16 listening test Outside front door opened




Frequency response Test #4-1 6-30-16 100db in hall music c scale




Frequency response Test #4-2 6-30-16 outside front door of hall c scale music



Frequency response Test #4-3 6-30-16 100db music all closed at 13 Walpole Rd.



Frequency response Test #4-6 6-30-16 100db music at barns c scale



Frequency response Test #4-2 6-30-16 100db music front door & back windows open c scale at 13 Walpole Rd.

