

August 3, 2009

Williamsburg School Committee
PO Box 573
1 Petticoat Hill Road
Williamsburg, MA 01096-0573

RE: Mechanical/Electrical System Analysis
Anne T. Dunphy Elementary School
Williamsburg, Massachusetts

Dear Ms. Nardi:

Attached, please find three (3) copies of our report entitled "Mechanical/Electrical Systems Analysis – Anne T. Dunphy Elementary School, Williamsburg, Massachusetts". In it is contained a description of existing conditions, deficiencies, recommendations, and cost estimate for all recommended improvements.

Let me take this opportunity to thank you and the Director of Maintenance for your excellent cooperation and input in the development of this report. We are confident that when implemented, the results will be a well planned and mechanically sound educational environment for the students and staff of this most important facility.

Very truly yours,

Dino J. D'Angelo
Principal